


# 平成29年度 航行規制ブイ破損状況



①



11-1(ポール折れ)  
H29.7.8.松原沖



11-1(修繕)  
H29.7.8.松原沖



11-1(ポール折れ)  
H29.8.12.松原沖



11-1(修繕)  
H29.8.14.松原沖

②



5-3(ポール折れ)  
H29.6.24.須越沖



5-3(修繕)  
H29.7.15.須越沖

③



8-1(ポール折れ)  
H29.9.10.横江浜沖



8-1(修繕)  
H29.9.10.横江浜沖

④



5-7(ポール折れ)  
H29.6.4.中浜沖



5-7(修繕)  
H29.6.4.修繕

⑤



No.なし(ポール折れ)  
H29.8.12.南浜沖



No.なし(修繕)  
H29.8.14.南浜沖

⑥



17-2(ポール折れ)  
H29.8.19.南浜沖



17-2(修繕)  
H29.9.2.南浜沖

⑦



4-10A(ポール折れ)  
H29.9.2.八屋戸浜沖